



1161

FIG. 1




2161

FIG. 2




3/61

FIG. 3



4/61

FIG. 4



5/61






FIG. 5

FIG. 6




7161

FIG. 6A



8/61

FIG. 7



91/61

FIG. 8






FIG. 10




13/61

FIG. 12




14/61

FIG. 12A




15/61

FIG. 13



16/61

FIG. 14



17/61

FIG. 15





FIG. 16



18161

FIG. 17






FIG. 18




20161

FIG. 19




21161



22/61

FIG. 21



23161

FIG. 21A




FIG. 21B




FIG. 21C





FIG. 22



25161

FIG. 22A





FIG. 23



26161

FIG. 24






FIG. 25



28161

FIG. 26



21/61

FIG. 27






FIG. 28



31 / 61

FIG. 29

1200



32161




FIG 30

33/61





FIG 31

FIG. 32



35161




FIG 33

36161

FIG. 34




FIG. 35





FIG. 36


38161

FIG. 37



39/61

FIG. 38






FIG 38 A




FIG 38 B





FIG 38 C

41 / 61

FIG. 39



42/61

FIG. 40






FIG. 41



43/61

FIG. 42



44/61




FIG. 43

45/61

FIG. 44




FIG. 45





FIG. 46



47/61





FIG 47

48/61

FIG. 48



49/61






FIG. 51



[illegible]

52161








FIG 53

53/61


FIG. 54



54161



55/61






FIG 57





FIG 58



57161

FIG. 59






FIG. 60



58/61



59/61




FIG 62

60/61




FIG 63

61/61

2000



2010

providing a bone plate having a head portion for cooperation with the condylar portion and a body portion for cooperation with the shaft portion and a first opening in the head portion and a second opening in the body portion

providing a first fastener

2012

securing the head portion of the bone plate to the condylar portion of the bone with the first fastener

2014

providing a second fastener

2016

securing the body portion of the bone plate to the shaft portion of the bone by percutaneously securing the second fastener to the body portion of the plate and to the shaft portion of the bone while urging the shaft portion of the bone toward the condylar portion of the bone

2018

FIG 64